



INSPECTION REPORT

Table with 4 columns: To, From, Attn, Report Date. Values: XXXXX, XXX, XXX XXX, XXX.

Table with 2 columns: Field, Value. Fields: Vendor Name, Factory Name, Factory Address, Order No. / PO No., Product description, Inspection Date.

Inspection Method Applied: (ANSI / ASQ Z1.4- 2008)

Table for inspection method details including sampling plans, AQL levels (Critical, Major, Minor), and sample size.

Inspection Criteria :

Table for inspection criteria with checkboxes for Purchase Order, Reference sample, Product Specifications, Artwork, Other documents, N/A.

Overall Result: [X] PASS [] FAIL [] PENDING [] ABORTIVE

Table for inspection results with 5 parts and columns for Conformed, Not Conformed, Pending.

Special Attention:

Table for special attention with 3 rows: Fail Reason Highlight, Pending Reason Highlight, Informative Remark.

Inspector Signature : XXX Factory Signature : XXX

1. PO Quantity & Availability: [X] Conformed [] Not Conformed [] Pending



Article	PO No.	PO QTY	Booked QTY	Actual QTY	% Finished	% Packed
4325753	47-0002080773	720	720	720	100	100
4325753	47-0002080775	720	720	720	100	100
Total:		1440	1440	1440	100	100

2. AQL (Workmanship appearance & Function inspection findings) Conformed Not Conformed Pending

Defect description	Critical	Major	Minor
Over painting on board	0	0	1
Poor painting on board	0	0	2
Scratch mark on board	0	2	1
Total defectives:	0	2	4
Maximum allowed:	0	7	10

3. Field Test / On Site Test Results: Conformed Not Conformed Pending


Article	Test item	Sample size	Result	Remark / Findings
4325753	Barcode scan	5pcs	pass	
4325753	Assembly check	3pcs	pass	
4325753	Stability check on 10 degree inclined plane	3pcs	pass	
4325753	3M tape test check	3pcs	pass	
4325753	Humidity check	3pcs	pass	(12, 12, 12), (10, 12, 12), (12, 10, 12)
4325753	Carton drop test	1ctn	pass	

4. Packaging & Product Conformity Conformed Not Conformed Pending

Article	QTY/ CTN	QTY/ Inner	Shipping Mark	Products	Bar Code On Unit	Bar Code On carton	Bar code Readable
	X- Ply	X- Ply					
4325753	2	/	conform	conform	4897021251322	N/A	Yes

Remark: compare with client' ref sample, artwork, shipping mark, PO.

SHIPPING MARK (MAIN MARK)	SHIPPING MARK (SIDE MARK)
-----------------------------	-----------------------------



5. Product Size & Weight Check

Conformed Not Conformed Pending

L,W, H: For Length, Width, Height, Unit: CM

Wt: For Weight, Unit: KG

Article	Data In PO/ Ref. Sample				Sample 1				Sample 2				Sample3			
	L	W	H	Wt	L	W	H	Wt	L	W	H	Wt	L	W	H	Wt
4325753	74	45	30	6.52	74	45	30	6.56	74	45	30	6.54	74	45	30	6.56

Carton Size & Weight Check

L,W, H: For Length, Width, Height, Unit: CM

Wt: For Weight, Unit: KG

Article	Data In PO				Outer Carton 1				Outer Carton 2				Pallet			
	L	W	H	Wt	L	W	H	Wt	L	W	H	Wt	L	W	H	Wt
4325753	62	39	50	22	61.5	39	49	21.6	61.5	39	49	22.5	/	/	/	/

Remark: compare with client' ref sample, shipping mark, PO data.

6. Attachment



def-over painting on board.JPG



def-poor painting on board-1.JPG



def-poor painting on board-2.JPG



def-scratch mark on board-1.JPG



def-scratch mark on board-2.JPG



def-scratch mark on board-3.JPG



export carton.JPG



individual packing.JPG



inner packing-1.JPG



inner packing-2.JPG



inner packing of color box.JPG



inner packing of color box (1).JPG



inner packing of color box (2).JPG



product packing-1.JPG



product packing-2.JPG



storage.JPG



storage (1).JPG



shipping mark-1.JPG

side mark-1.JPG



marking on color box.JPG

marking on color box (1).JPG



marking on color box (2).JPG



marking on color box (3).JPG



marking on color box (4).JPG



marking on color box (5).JPG



marking on color box (6).JPG

marking on color box (7).JPG



marking on color box (8).JPG



marking on color box (9).JPG



marking on color box (10).JPG



marking on color box (11).JPG



marking on color box (14).JPG



marking on color box (15).JPG



marking on color box (16).JPG



marking on color box (17).JPG



marking on color box (18).JPG

marking on accessories box.JPG



marking on accessories packing bag.JPG



instruction sheet.JPG



marking on product (3).JPG



marking on product.JPG





shipping mark-2.JPG



marking on product (2).JPG



side mark-2.JPG

marking on product (4).JPG



carton weight check.JPG

weight check-1.JPG



barcode scan.JPG



weight check-2.JPG



carton drop test.JPG



size check.JPG



function check.JPG



function check (1).JPG



3M tape test.JPG



3M tape test (1).JPG



humidity check (1).JPG



humidity check (2).JPG



humidity check.JPG



gate of factory.JPG



product&ref.smample-1.JPG



product-1.JPG



accessories.JPG



product-2.JPG



product-3.JPG



assembly product.JPG



assembly product (1).JPG



assembly product (2).JPG



assembly product (3).JPG



assembly product (4).JPG



product&ref.sample-2.JPG

TIS Sample Report